



Project Logo: 	Project Name: VVIP Beach Villa at Al Khor			Form No.: P07-F107 Rev. 01 / Feb. 2012
	Project No.: SP/C/1616/14		Client:	Project Manager:
Contractor: 				

MATERIAL APPROVAL REQUEST (MAR)

Submittal Contents: <input type="checkbox"/> - Material/Sample <input type="checkbox"/> - Mock-up <input checked="" type="checkbox"/> - Catalogue/Brochure <input type="checkbox"/> - others Colour Card	MAR No.: ALB-MS-BV-AR-0409 Rev. 0
Date Submitted: 30-Jan-2017	

Trade / Discipline: <input type="checkbox"/> - Civil <input checked="" type="checkbox"/> - Architectural <input type="checkbox"/> - Electrical <input type="checkbox"/> - Information Tech. (IT) <input type="checkbox"/> - Structural <input type="checkbox"/> - Mechanical <input type="checkbox"/> - Plumbing <input type="checkbox"/> - Others <input type="checkbox"/> - Landscape <input checked="" type="checkbox"/> - Interior Design	Date Required on Site: 31-Jan-2017 Production Period: One week Total Delivery Time: As required Expected Arrival on Site: As approved
--	--




Description of Material / Equipment: **Material Submittal for VVIP Beach Villa NoiseControl Acoustic Tratment Work at AHU Rooms Chiller Walls, Chiller Louvers, Heat Pump location supply and installation by Hill Pont Building Solution.**

1. Acoustic Spray - Diathonite Acoustix

2. Louvers - Accustop - Hat Type Louvers

References: a.) Specs. Ref. : Acoustic Report Rev 01 . June 2016 b.) Drawing Ref. : AHU Rooms ,Chiller Plant Pump Room ,Yard c.) BOQ Ref. : NIL - VARIATION Others :	c.) QCS 2010 Ref. : NIL d.) Statutory Req. : Nil e.) Specified Vendors List : Complies
---	---

Manufacturer / Supplier Details: <input type="checkbox"/> - Locally Manufactured <input checked="" type="checkbox"/> - Imported Country of Origin: Italy	
a.) Local Supplier / Agent: Company Name: HILL POINT BUILDING SOLUTIONS Address / Contacts: BOHA - CRATAGE	b.) Manufacturer : Company Name: DIASEN Srl - Improve Your Building Address / Contacts: Berbentina, 5, 60041 Sassoferrato AN, Italy

Prepared by: (Contractors PE or CM or Architect)  Name / Sign / Date: Ramakrishna 22/1/17	Verified by: (Contractors QA/QC, QS, or Proj. Coordinator)  Name / Sign / Date: [Signature]	Recommended for Approval by: (Contractor's PM)  Name / Sign / Date: [Signature]
---	---	---

COMMENTS BY THE CONSULTANT

Comments: Mechanical - B (Approved as Noted - Refer to attached comments for compliance)

SEE ATTACHED COMMENTS SHEET

(Use a separate comments sheet when necessary, for easy traceability purposes do not forget to include the MAR No., Revision No., & corresponding date of this MAR to the comments sheet)

Submittal Status: <input type="checkbox"/> - A - Approved <input checked="" type="checkbox"/> - B - Approved as Noted <input type="checkbox"/> - C - Revise and Resubmit <input type="checkbox"/> - D - Rejected

Supervision Consultant Signature:  Name & Signature: Leandro A. Vergara / Jett de Guzman RE or Senior Engineer: 06 Feb. 2017 Designation: [Blank] Date: [Blank]	Client Approval / Endorsement (when required) :  Name & Signature: Shibu George Project Manager: 6/2/2017 Designation: [Blank] Date: [Blank]
--	---

Approval or comments to the submittals does not relieve the Contractor from their responsibilities. The assessment is to review the general conformance and compliance of the submittal to the contract and specification requirements.